



Specification Summary

NO-A1	NO-AE	NO-B1	NO-D4
0 to 250	0 to 5,000	0 to 250	0 to 100
320 to 480	40 to 80	400 to 620	450 to 600
< 0.2	< 1	< 0.15	< 0.1
< 45	< 75	< 30	< 15
0 to 2	0 to 15	0 to 4	0 to 1.5
800	10,000	1,200	400
> 24	> 24	> 24	> 24
-30 to 50	-30 to 50	-30 to 50	-20 to 50
80 to 120	80 to 120	80 to 120	80 to 120
15 to 90	15 to 90	15 to 90	15 to 90
10 to 47	10 to 47	10 to 47	10 to 47

ent environments unless otherwise stated. As applications of use are outside our control, the responsibility. Customers should test under their own conditions, to ensure that the sensors

Alphasense sensors. Soldering, gluing or other methods of connection will void your warranty.